
## Purble zinc-cobalt





	Pb7	
Silica	26	
Kaolin (EPK)	12	
Potash Feldspace (Cluster)	25	
Whiting	10	
Gerstley Borate (Laguna)	18	
Talc	9	
Zinc Oxide	0, 2, 4, 6 left to right	
Cobalt Carbonate	0, 0.5, 1.0, 1.5 top to bottom	

The base glaze (top left) is satin, somewhat milky, and has no visible crazing.

The cobalt only test has no depth or mottling.

My preference for further testing will focus on 0.75 cobalt and 4 zinc oxide. This are has the best balance of mottling or lavender and blue colors.

The intention of "purble" was a purple-hued blue from magnesium and zinc.