



## BA2

Silica	20
Kaolin (EPK)	8
Ball Clay (OM4)	7
Potash Feldspace (Cluster)	32
Talc	5
Gerstley Borate (Laguna)	8
Frit 3134	10
Bone Ash	10
Copper Carbonate	0, 1, 2, 3 left to right
Zicropax	0, 3.3, 6.6, 10 top to bottom

Base glaze (top left) shows coarse crazing. Surface is semi-gloss and cloudy. When too thick, this glaze is prone to pitting and smooth craters. No signs of running.

The 10% zirconium glaze (the reason behind this test) appears to be very nice.